


E-ZLIFT Troughing Slider Conveyor TS-050 with Direct Drive for 14", 18" & 24" Wide Belts Parts List & Schematic



Denver, CO USA www.ezliftconveyors.com North American Toll Free: 1-800-821-9966 Denver Local: 303-733-5533





Denver, CO USA www.ezliftconveyors.com

E-ZLIFT Troughing Slider Conveyor TS-050 Full Parts List Including Belting and Lacing

| Part# 149 149A 149B 149C 153A 157 157G 162 175B-BM 175A 175B-30 1" 175B-30 1" 175B-30 1-1/4" 175MSH 193 193TR 194 194 194 194TR Rubber cover | Description 1" Bearing w/ 3-hole Triangular Flangettes 1" Bearing w/ Rectangle/Oval Flangettes 1-1/4" Bearing w/ 3-hole Triangular Flangettes 1-1/4" Bearing w/ 2-hole Oval Flangettes 5/8" Bearing w/ 2-hole Oval Flangettes Handle for Motor/Reducer Assembly Direct Drive Motor Guard (with #157 handle) Boot Mount for Size 50 Reducer Boot Mount for Size 60 Reducer Size 50 Reducer w/ 1" hollow bore Size 60 Reducer w/ 1" hollow bore Size 60 Reducer w/ 1-1/4" hollow bore Motor Support Hardware 1 hp 115V 56C TEFC motor Thermal Reset Button for Baldor 1 hp 3510M motor 1-1/2 hp 115V 56C TEFC motor Thermal Reset Button for Baldor 1-1/2 hp 3514M motor Rubber Cover for Thermal Reset Button |
|---|--|
|---|--|

| Part# | Description |
|-----------------|-------------------------------------|
| 195B | Start/Stop switch |
| 197A | 5" long steel idler top roller |
| 198A | 11" long steel idler top roller |
| 328 -xx | Drive Pulley w/ 1" bore* |
| 330 -xx | Drive Pulley w/ 1-1/4" bore* |
| 348A -xx | Drive Shaft w/ 1" O.D.* |
| 350A -xx | Drive Shaft w/ 1-1/4" O.D.* |
| 399 -xx | Return Wheels w/ 5/8" shaft* |
| 399MB | Mounting bracket for return wheels |
| 399MBslot | Return wheel/roller weld-on bracket |

* **xx** denotes conveyor belt width (14", 18", or 24")

Complete Belt Assemblies

| Part# | Description |
|-----------------|--|
| 323- x-y | Belt for model ${f x}$ conveyor with ${f y}$ cleat option* |

Example:

- 323-73-18-2 Belt for model 73-18 conveyor with 2 cleat option (2" high cleats on 48" centers)
- * **x** = conveyor model number
- y = 2, 2" high cleats on 48" centers
- = **mcb**, 3/16" high continuous mini cleat
- = **s**, smooth belt (no cleats)


| Part# | Description |
|----------------|--|
| 216 | Adjustment housing w/ 1" bearing |
| 216A | 1" Bearing insert for housing |
| 217 | Adjustment frame w/ screw for 1" bearing |
| 218 | Adjustment housing w/ 1-1/4" bearing |
| 218A | 1-1/4" Bearing insert for housing |
| 219 | Adjustment frame w/ screw for 1-1/4" bearing |
| 220 | 5/8" All-thread screw for adjustment frame |
| 329 -xx | Tail Pulley w/ 1" bore* |
| 331 -xx | Tail Pulley w/ 1-1/4" bore* |
| 349 -xx | Tail Shaft w/ 1" O.D.* |
| 351 -xx | Tail Shaft w/ 1-1/4" O.D.* |

* **xx** denotes conveyor belt width (14", 18", or 24")

Belt Parts

| Part# | Description |
|--------------------|--|
| 307-2- xx | Set of (3) 2" bolt on Cleats for -xx wide belt* |
| 323 -xx | -xx wide 2 ply 1/8" x FS belting / ft.* |
| 325-M10 -xx | Set of -xx long Screw Lacing w/ 10mm screws* |
| 326 -xx | Set of #RS187 x -xx long Staple Lacing*, ** |
| | |

* **xx** denotes conveyor belt width (14", 18", or 24") ** requires #326-4 tool for assembly



Multilift, Inc. Denver, CO USA www.ezliftconveyors.com